

# Machine Studies

## Schedule for Run2-6,2000

June 12th, 0800 - June 12th, 1600

<b>Time</b>	<b>Descriptions</b>	<b>Studios</b>	<b>SRStatus</b>
<b>Monday, 6/12/01</b>			
<b>0800-1030</b>	<b>ACIS-to-shutter link. Zone B access.</b>	<b>Ross Forrestal</b>	<b>Stored beam and injection</b>
<b>1030-1330</b>	<b>Xray bpm study</b>	<b>Singh</b>	<b>Stored beam and injection</b>
<b>1330-1430</b>	<b>Operator training</b>	<b>OPS</b>	<b>Stored beam and injection</b>
<b>1430-1500</b>	<b>Bunch cleaning</b>	<b>Yao</b>	<b>Stored beam and injection</b>
<b>1530-1600</b>	<b>Set up User beam</b>	<b>OPS</b>	<b>Stored beam and injection</b>