

Machine Studies

Schedule for Run2-6,2003

July 4th, 0800 - July 5th, 0800

Time	Descriptions	Studiers	SRStatus
Friday, 07/04/03			
0800-0900	Zone F access to check sector 40 ik4 downstream bellows top air cooling blower hose during next machine intervention.	Putnam	No beam
0800-1000	Control access to Zone-D to lock 23ID shutter, LOTO switch gear required	Merritt	No beam
0800-0900	Replace erratic SR absorber Love controller in sector 40 circuit 1.	Putnam	No beam
1000-1800	X-BPM feedback/feedforward	Decker	Stored beam and injection
1800-2400	Single bunch studies vs rf freq. Injection is required.	Harkay	Stored beam and injection
Saturday, 07/05/03			
0000-0200	Operator storage ring training	Christensen	
0200-0500	RTFB instability study	Emery	Stored beam and injection
0500-0700	Studies time available		Stored beam and injection
0700-0800	Singlet fill pattern, low emittance, top-up user beam	OPS Yao	Stored beam and injection